

The damage of road embankment which was caused by the chuetu-earthquake

Takashi Hosoya[1]; Tomoo Hashimoto[2]; Kazuo Sakagawa[1]; Shinnichi Ogata[3]

[1] CKC; [2] Chuokaihatsu Co; [3] Chuo Kaihatu Co.Ltd.

The chuetu-earthquake was happened 23 Sep 2004. We examined road embankment damage of there. We were studying as follows.

1. The range of road embankment damage.
2. Relation between the road embankment damage and high of there.
3. Relation between road embankment damage and type of there.
4. Relation between road embankment damage and geographical features or geological features of there.
5. Relation between road embankment damage and difference of road standard. We could see road embankment damage where Japanese earthquake level over 5up and We will show the tendency of road embankment damage place by place.