

Publication of Disaster Damage Map of Noto Hanto Earthquake in 2007, using Cyber Japan web mapping system

toshio kitahara[1]; Junichi Kisanuki[2]; Tatsuo Sekiguchi[3]

[1] none; [2] Geographical Survey Inst.; [3] GSI

Based on aerial-photographs taken in an urgent mission in response to Noto Hanto Earthquake on March 25 2007, Geographical Survey Institute (GSI) identified earthquake damages such as landslide, road destruction and areas suffering ground liquefaction in coastal areas in Wajima City and the northern part of Shika town. In addition, positional information and photographs of damages were added as the result of a ground truth survey by GSI immediately after the earthquake. These results were cartographically compiled and eventually released to the public as Disaster Damage Map of Noto Hanto earthquake in 2007 on Cyber Japan web mapping system through GSI web site (URL:http://zgate.gsi.go.jp/notojishin/noto_saigai.html) on 4 April. 2007.