## **Japan Geoscience Union Meeting 2010**

(May 23-28 2010 at Makuhari, Chiba, Japan)

## ©2009. Japan Geoscience Union. All Rights Reserved.



MIS007-10

会場: 304

時間: 5月24日16:15-16:30

## 神岡鉱山内南東部断層での水理試験

## Hydraulic test around a fault in Kamioka mine

加納 靖之1\*, 伊藤 久男2, 木下 正高2

Yasuyuki Kano<sup>1\*</sup>, Hisao Ito<sup>2</sup>, Masataka Kinoshita<sup>2</sup>

<sup>1</sup>京大·防災研,<sup>2</sup>海洋研究開発機構

<sup>1</sup>DPRI, Kyoto Univ., <sup>2</sup>JAMSTEC

A new hole was drilled into a fault (the Southwest fault) in Kamioka mine, Gifu prefecture, central Japan Primal target of the borehole is to develop relevant method to determine hydraulic properties of a fault, which usually difficult to measure, by examining hydraulic properties of a fault obtained from several methods such as in-situ hydraulic test, estimation from logging and core analyses and. The borehole is vertical with total depth of 23.5 m, and diameter of 98 mm. The host rock of the formation around borehole is gneiss. The borehole penetrate the fault from around the interval between 19.5 m and 23.1 m. Sharp boundary was observed at around depth of 19.5 m and intensively crashed zone with small amount of clay continues to 23.1 m. A small and thin crack is observed around 8.9 m. The core is recovered for all the depth of the borehole. An obtained optical borehole and televiewer images of the borehole, and ultrasonic velocity log around the borehole are also obtained. We carried out a series of hydraulic tests using packers just after the drilling. To measure hydraulic properties of the fault, we made a single packer test that isolates the interval below 19.0 m by a packer. To obtain the hydraulic properties of host rock and the small crack, we made dual packer tests that isolate intervals of 13.9-15.1 m and 8.3-9.5 m using two packers. We also measure the water level change during each test, which provide another estimate of hydraulic properties of the fault. Preliminary estimate of permeability from water level measurement is  $2x10^{-15}$ m<sup>2</sup>. The permeability of the host rock is three orders of magnitude larger than that of the fault. The small crack at about 8.9 m exhibits permeability between those of the fault host rock. This large deference in permeability between the fault and host rock suggests that the fault serve as a channel of fluid flow in the surrounding region.

キーワード:透水係数,断層の構造,検層,孔内測定,神岡鉱山

Keywords: permeability, fault structure, logging, downhole measurement, Kamioka mine