

ネパール国北部山間部における地滑りと少数民族の生活環境について

Land slide and living conditions of minority in the northern part of mountain area, Nepal

\*桑原 祐史<sup>1</sup>

\*Yuji Kuwahara<sup>1</sup>

1.茨城大学工学部都市システム工学科

1.Department of Urban and Civil engineering, school of Engineering, Ibaraki University

In Apr.2015, M7.8 earthquake occurred in Nepal. It was confirmed the building damage in an urban area and the landslide damage in a mountainous region by a field survey in 2015. Especially, in mountainous region, we found the minority people who can't get accident support. So, today, I will talk about the field survey results in Nepal.

キーワード：地震災害、地滑り、少数民族、衛星画像

Keywords: seismic hazard, land slide, minority, satellite image